



SKYSPAN SHADE
COMMERCIAL UMBRELLAS AND SHADE STRUCTURES



Sunset
Corrosive Environment

Maintenance

Corrosive Environment Sunset Umbrella Maintenance Schedule

This should be carried out Three Monthly

1. Using a grease gun, apply approximately 100ml of high temperature wheel bearing grease to main gear via the winding handle keyway approximately 3-4 pumps per 5 revolutions. This ensures the grease is evenly dispersed onto internal gearing of the mechanism
2. Wash frame and canopy with a PH neutral non-abrasive detergent, be sure to rinse thoroughly.
3. Check that all nuts and bolts are secure, and the umbrella is tensioned correctly, and the Anti-creep latch is engaged.
4. Apply silicon spray on all stainless-steel parts including winding hub.

SKYSPAN SHADE

Office / Factory Unit 1, 4 Old Pacific Highway, Yatala, Queensland 4207, Australia

Tel: +61 (0) 7 3804 6288 Email: sales@skyspanshade.com.au

www.skyspanshade.com.au