



SKYSPAN SHADE
COMMERCIAL UMBRELLAS AND SHADE STRUCTURES



Vista
Corrosive Environment

Maintenance

Corrosive Environment Vista Umbrella Maintenance Schedule

This should be carried out Three Monthly

1. Apply high temperature wheel bearing grease to lead screw of the mechanism (a thin line down either side is sufficient).
2. Wind the umbrella down and back up to evenly distribute the grease up the lead screw.
3. Check that all nuts and bolts are secure, and the umbrella is tensioned correctly, engage Anti-creep latch.
4. Wash the frame and canopy with a non-abrasive PH neutral detergent and rinse thoroughly.
5. Apply silicon spray on all stainless-steel parts including the area the mid-cast travels.

SKYSPAN SHADE

Office / Factory Unit 1, 4 Old Pacific Highway, Yatala, Queensland 4207, Australia

Tel: +61 (0) 7 3804 6288 Email: sales@skyspanshade.com.au

www.skyspanshade.com.au